



Dart Aerospace Ltd.  
1270 Aberdeen St  
Hawkesbury, ON  
K6A 1K7  
Canada

Tel (613) 632-5200  
Fax 613 632-5246

## ENGINEERING CHANGE REQUEST

### ECR 223

<b>Date Opened:</b>	6/17/21 3:58 PM	<b>Requested By:</b>	Gagnon-Donovan, Michelle
<b>Type:</b>	Tooling/DSK/GSE Drawing Change	<b>Responsible Engineer:</b>	Drouin, Steven
<b>Priority:</b>	Medium	<b>Requester*:</b>	Gagnon-Donovan, Michelle
<b>Status:</b>	Quality Disposition	<b>DE Approver*:</b>	Drouin, Steven
<b>Reason:</b>		<b>ECR Lead*:</b>	Drouin, Steven
<b>Expense:</b>	0		
<b>Target Date:</b>			
<b>Execution Date:</b>			
<b>ECR Approval No:</b>			
<b>RE (R&amp;D):</b>		<b>**BRIEF DESCRIPTION**:</b>	<b>RBW1205G00132-3G to be placed under review</b>
<b>Status Note:</b>		<b>DESCRIPTION/ ADR CONTENT**:</b>	RBW1205G00132-3G and subcomponents to be placed under review RBW1205G00132-3G RBWA353A04 and subcomponents to be placed under review

### CUSTOMER APPROVALS

Customer	Customer Visible	Customer Approval Required	*	Customer Approved
----------	------------------	----------------------------	---	-------------------

### PARTS

Part No	Rev	Part Status	Name	Type	Customer Part	Special Comments	Documents
RBW1205G00132-3G		On hold	Helicopter Servicing	Tools & GSE	RBW1205G00132-3G RBW1205G00132-3G		RBW1205G00132-3G-RevJ-DEV.pdf

[https://www.plexonline.com/e99a7681-8d15-464c-8c7f-10032bc8591c/Plexus\\_Control/Report\\_View/Viewer\\_2.asp?URL=../ecr/ecr\\_print.asp&ECR\\_Key=78...](https://www.plexonline.com/e99a7681-8d15-464c-8c7f-10032bc8591c/Plexus_Control/Report_View/Viewer_2.asp?URL=../ecr/ecr_print.asp&ECR_Key=78...) 2/4

[https://www.plexonline.com/e99a7681-8d15-464c-8c7f-10032bc8591c/Plexus\\_Control/Report\\_View/2.asp?URL=../ecr/ecr\\_print.asp&ECR\\_Key=78...](https://www.plexonline.com/e99a7681-8d15-464c-8c7f-10032bc8591c/Plexus_Control/Report_View/2.asp?URL=../ecr/ecr_print.asp&ECR_Key=78...) 3/4

INVENTORY DISPOSITION				
Part No Revision	Material No	Current Inventory Qty	Purchasing On-Order Qty	Qty Scheduled for Production
RBW1205G00132-3G		1 Quarantine	0 *	0 *
RBW1205G00132-3G-11		2 *	0 *	0 *
RBW1205G00132-3G-13		0 *	0 *	0 *
RBW1205G00132-3G-19		0 *	0 *	0 *
RBW1205G00132-3G-25		0 *	0 *	0 *
RBW1205G00132-3G-9		2 *	0 *	0 *
RBW1205G00132-3GE		0 *	0 *	0 *
RBW1205G00132-3GP		0 *	0 *	0 *
RBWA353A04		0 Quarantine	0 *	0 *
RBWA353A04-PO		0 *	0 *	0 *
RBWA353A04-01		0 *	0 *	0 *
RBWA353A04-02		0 *	0 *	0 *
RBWA353A04-03		0 *	0 *	0 *
RBWA353A04-05		0 *	0 *	0 *
RBWA353A04-06		0 *	0 *	0 *
RBWA353A04-07		0 *	0 *	0 *
RBWA353A04-08		0 *	0 *	0 *
RBWA353A04-1		0 *	0 *	0 *
RBWA353A04-19		5 *	0 *	0 *
RBWA353A04-2		0 *	0 *	0 *
RBWA353A04-24		0 *	0 *	0 *
RBWA353A04-3		0 *	0 *	0 *
RBWA353A04-5		0 *	0 *	0 *
RBWA353A04-6		0 *	0 *	0 *
RBWA353A04-7		0 *	0 *	0 *
RBWA353A04-8		0 *	0 *	0 *
RBWA353A04P		0 *	0 *	0 *
EFFECTS				
Effect Group	Effects			
1. Quarantine?	Immediate quarantine required (RBW1205G00132-3G RBWA353A04)			